

Accumulator Piston Kit

Part No.

95740-15K


- Pistons (7)
- Springs (7)

NOTE: Also fits Ford CFT23

Patent No. 8,794,108

Application Units	Accumulators Needed
Chrysler 845RE	7
Ford 6F35 (Gen. 1)	1
Ford 6F35 (Gen. 2)	1
Ford 6R60/6R80	6*
Ford 6R140	3*
Ford CFT23	5
Ford CFT30	5
ZF6HP19/26/32 (Gen. 1)	6
ZF6HP21/28/34 (Gen. 2)	7
ZF8HP45/55/70	7
*NOTE: Sometimes these require 2.	

Chrysler 845RE, Ford 6F35 (Gen. 1), 6F35 (Gen. 2), 6R140, 6R60, 6R75, 6R80, CFT30; ZF6HP19, ZF6HP21, ZF6HP26, ZF6HP28, ZF6HP32, ZF6HP34, ZF8HP45, ZF8HP55, ZF8HP70



1. Disassembly

Remove OE accumulator pistons (with attached bumpers) and discard.

2. Installation & Assembly

- Ensure accumulator bores are cleaned and clear of dirt and debris.
- Install one Sonnax spring in each bore.
- Install one Sonnax accumulator piston in each bore, open side toward spring.