


## Lockup Control Boost Valve Kit

Part No.

**47740-06K**

- Valve
- Sleeve

## Toyota/Lexus U660E, U660F, U760E, U760F



### 1. Disassembly

- Remove and discard OE lockup control boost valve and sleeve.
- Save OE retainer for reuse.

### 2. Installation & Assembly

- Install the Sonnax lockup control boost valve and sleeve.
- Replace OE retainer pin to secure the lockup control boost assembly in the bore.

### 3. Final Testing

Vacuum testing at the port(s) indicated holds the recommended minimum 18 in-Hg.

